

RPG Surface Prep and Industrial Services

496 Fricks Lock Road, Pottstown, PA 19464 • www.rpgsurfaceprep.com

FERRIC TRENCH REFUBISHMENT AND LINING

Original condition, surface prep and Aquafin Crack Injection











Aquafin Mortar Repair, Aquafin Moisture Mitigating Primer and ErgonArmor Epoxy Primer











ErgonArmor 210 first coat and second coat then ErgonArmor TuffChem II on all vertical and horizontal transitions.











One of our most complicated and challenging refurbishment and lining projects to date. If you have a challenging application, call us for an evaluation today.